

WorkList

	A	B	C	D	E	F	G	H	I	J
1	LabNumber	Analysis	Sampled	Status	Project	SampleName	SampleType	SampleComments	Canister ID	SampleInfo2
2	8111508-01	TO-15 2018	11/14/18 10:22	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	VOID Col 1 Start 10:22 11/13/18 Probe #10314 - >3" difference from field to lab	5079	3.50" Hg
3	8111508-03	TO-15 2018	11/14/18 10:00	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 10:00 11/13/18 Probe #10315	A21028	2.00" Hg
4	8111508-04	TO-15 2018	11/14/18 10:00	Reported	EtO Region 5	WB Trip Blank	Field Sample	Trip Blank	5037	29.50" Hg
5	8111508-02	TO-15 2018	11/14/18 10:23	Reported	EtO Region 5	WB Village Hall C2	Collocated - C2	VOID Col 2 Start 10:23 11/13/18 Probe #10313 - >3" difference between field and lab	SAT057	1.00" Hg
6	8112012-01	TO-15 2018	11/17/18 10:07	Reported	EtO Region 5	WB Village Hall	Field Sample	Start 10:24 11/16/18 Probe #10313	A21096	2.00" Hg
7	8112012-02	TO-15 2018	11/17/18 09:57	Reported	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 10:09 11/16/18 Probe #10314	SAT085	2.50" Hg
8	8112012-03	TO-15 2018	11/17/18 09:57	Reported	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 10:09 11/16/18 Probe #10315	SAT114	3.50" Hg
9	8112113-01	TO-15 2018	11/20/18 09:30	Reported	EtO Region 5	WB Village Hall C1	Collocated - C1	Col 1 Start 09:32 11/19/18 Probe #10315	A21102	2.00" Hg
10	8112113-03	TO-15 2018	11/20/18 09:21	Reported	EtO Region 5	WB Warehouse	Field Sample	Start 09:20 11/19/18 Probe #10314	5077	3.50" Hg
11	8112113-04	TO-15 2018	11/20/18 10:36	Reported	EtO Region 5	Gower ES	Field Sample	Start 10:36 11/19/18 Probe #10293	SAT092	3.50" Hg
12	8112113-05	TO-15 2018	11/20/18 09:39	Reported	EtO Region 5	Gower MS	Field Sample	Start 09:46 11/19/18 Probe #10311	18879	2.00" Hg
13	8112113-06	TO-15 2018	11/20/18 10:10	Reported	EtO Region 5	Willow Pond Park	Field Sample	Start 10:10 11/19/18 Probe #10294	SAT089	2.50" Hg
14	8112113-07	TO-15 2018	11/20/18 09:54	Reported	EtO Region 5	Watertower	Field Sample	Start 09:59 11/19/18 Probe #10312	SAT169	2.00" Hg
15	8112113-08	TO-15 2018	11/20/18 10:25	Reported	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:25 11/19/18 Probe #10076	A21051	4.00" Hg
16	8112113-09	TO-15 2018	11/20/18 10:45	Reported	EtO Region 5	West Neighborhood	Field Sample	Start 10:45 11/19/18 Probe #10310	SAT025	3.00" Hg
17	8112113-02	TO-15 2018	11/20/18 09:29	Reported	EtO Region 5	WB Village Hall C2	Collocated - C1	Col 2 Start 09:33 11/19/18 Probe #10315	SAT013	3.50" Hg
18	8112702-01	TO-15 2018	11/24/18 09:57	Received	EtO Region 5	Watertower	Field Sample	Start 09:57 11/23/18 Probe #10312	18877	3.50" Hg
19	8112702-02	TO-15 2018	11/24/18 10:44	Received	EtO Region 5	West Neighborhood	Field Sample	Start 10:44 11/23/18 Probe #10310	5015	5.00" Hg
20	8112702-03	TO-15 2018	11/24/18 09:41	Received	EtO Region 5	Gower MS	Field Sample	Start 09:36 11/23/18 Probe #10311	SAT135	3.00" Hg
21	8112702-04	TO-15 2018	11/24/18 10:35	Received	EtO Region 5	Gower ES	Field Sample	Start 10:35 11/23/18 Probe #10293	SAT097	4.50" Hg
22	8112702-05	TO-15 2018	11/24/18 10:09	Received	EtO Region 5	Willow Pond Park	Field Sample	Start 10:09 11/23/18 Probe #10294	SAT131	3.50" Hg
23	8112702-06	TO-15 2018	11/24/18 09:34	Received	EtO Region 5	WB Village Hall	Field Sample	Start 09:34 11/23/18 Probe #10313	5094	4.00" Hg
24	8112702-07	TO-15 2018	11/24/18 09:23	Received	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 09:21 11/23/18 Probe #10314	22327	3.00" Hg
25	8112702-08	TO-15 2018	11/24/18 10:23	Received	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:23 11/23/18 Probe #10076	SAT143	5.00" Hg
26	8112702-09	TO-15 2018	11/24/18 09:25	Received	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:25 11/23/18 Probe #10315	3225	4.50" Hg
27	8112702-10	TO-15 2018	11/26/18 09:52	Received	EtO Region 5	Watertower VOID	Field Sample	Void per site operator Start 09:39 11/25/18 Probe #10312	SAT004	18.50" Hg
28	8112702-11	TO-15 2018	11/26/18 09:27	Received	EtO Region 5	WB Warehouse C1	Collocated - C1	Col 1 Start 09:04 11/25/18 Probe #10315	SAT123	3.00" Hg
29	8112702-13	TO-15 2018	11/26/18 09:34	Received	EtO Region 5	WB Village Hall	Field Sample	Start 09:15 11/25/18 Probe #10314	5133	3.00" Hg
30	8112702-14	TO-15 2018	11/26/18 09:42	Received	EtO Region 5	Gower MS	Field Sample	Start 09:27 11/25/18 Probe #10311	5127	2.00" Hg
31	8112702-15	TO-15 2018	11/26/18 10:21	Received	EtO Region 5	Gower ES	Field Sample	Start 10:15 11/25/18 Probe #10293	5056	4.00" Hg
32	8112702-16	TO-15 2018	11/26/18 10:16	Received	EtO Region 5	Hinsdale South HS	Field Sample	Start 10:14 11/25/18 Probe #10076	5033	5.00" Hg
33	8112702-17	TO-15 2018	11/26/18 10:03	Received	EtO Region 5	Willow Pond Park	Field Sample	Start 09:50 11/25/18 Probe #10294	SAT037	1.90" Hg
34	8112702-12	TO-15 2018	11/26/18 09:25	Received	EtO Region 5	WB Warehouse C2	Collocated - C2	Col 2 Start 09:05 11/25/18 Probe #10313	5146	2.00" Hg